

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Problem Image Mailbox.**



Incandescent
Slit Lamp
Ramp Times

FIG. 1



Slit Laser
Ramp Times

FIG. 2

Interlaced Video Image
640 x 480 Pixels




FIG. 3



FIG. 4





FIG. 5

RAPID SWITCHING SLIT SCAN IMAGE CAPTURE SYSTEM
 Donald Charles Grove
 To be Assigned



RAPID SWITCHING SLIT-SCAN IMAGE CAPTURE SYSTEM
Donald Charles Grove
To be Assigned





FIG. 7 (Prior Art)

RAPID-SWITCHING SLIT-SCAN IMAGE CAPTURE SYSTEM
 Donald Charles Grove
 To be Assigned






Fig. 9




Figure 10.

RAPID SWITCHING SLIT SCAN IMAGE CAPTURE SYSTEM
Donald Charles Grove
To be Assigned




Figure 11: